



hip dac 3

Quick Set-Up



Set-Up video

XBass

PowerMatch

BAL 4.4mm output

S-BAL 3.5mm output

Analogue Volume Control / ON/OFF

Audio Format LED (kHz)

USB-C data input

USB-C (5V) charging input

Battery status LED

1 Connect to power supply (5V only)



Battery status LED

- 76% - 100%
- 26% - 75%
- 11% - 25%
- ☀ 0% - 10%

Turn ON




2 Input



3 Output



4 Audio Format & kHz LED



5 iEMatch

